



# Updated Technical Information



This information has been provided to you for the following reasons:

1. The AV outputs have been marked incorrectly on the wrong sides of the unit. AV1 & AV2 outputs should be on the left side. (same as the AV1 & AV2 inputs)
2. The AV3 & AV4 outputs should be on the right side. (same as the AV3 & AV4 inputs)

Original



Latest



## Button Layout

1. The buttons on the original remote are not labeled and differ from the new remote.
2. Look very carefully as buttons are marked on the diagram on both old and new remote.